Generic Inspection Form

| Inventory ID: | Asset Number | Anticipated Sale Price: |
|---|------------------------------|--------------------------------|
| Short Description: Seneral Year 70551h 9 Manufacturer | KOHLER | Model /25 ROZ 171 |
| Please fill in or check if apply | Long Description: | |
| This Equipment Is Operable Is Not Operable For Parts Only Needs Repair The Condition is Unknown Hours: 340 This equipment was maintained every YRLY Hours Days Serial # 218160 Repairs needed: DAY TANK LEAKS Repairs | | |
| Description of Use Showbary 5th | no By Generalor | |
| Color Base Minor damage to: | | ner Metal Plastic Wood Rubber |
| Major damage to: Size: Length: Feet: Inches: Height: Feet: Inches: Height: Feet: Inches: Women's Size: Women's Size: | | |
| Additional Equipment: Manufactur | rer Mo | odel |
| Serial # | | Needs repair Unknown Condition |
| | | odel |
| | _ Condition: ☐ Is Operable ☐ | Needs repair Unknown Condition |
| | | odel |
| Serial # Description: | • | Needs repair Unknown Condition |
| Comments: | | <i>,9</i> |
| | | |
| Location of Asset: <u>Sewer Othlity - 1139 EDWARDS RD</u> For more information contact: <u>JOHN PIETROWSKI</u> | | |