

# Generic Inspection Form

Inventory ID: \_\_\_\_\_

Asset Number \_\_\_\_\_

Anticipated Sale Price: \_\_\_\_\_

Short Description: Aluminium TRAILER STAGE

Year 87

Manufacturer CENTURY

Model 24'x40'

Please fill in or check if apply

Long Description:

This Equipment: ☒ Is Operable ☐ Is Not Operable ☐ For Parts Only ☐ Needs Repair ☐ The Condition is Unknown

☐ Hours: \_\_\_\_\_ This equipment was maintained every \_\_\_\_\_ ☐ Hours ☐ Days

Serial # Vin 1XCS40283H2000509

Repairs needed: \_\_\_\_\_

Description of Use

EVENT STAGE w/railings & STAIRS  
GVWR - 12,000

Color All Aluminium ☐ Cloth ☐ Vinyl ☐ Leather ☐ Metal ☐ Plastic ☐ Wood ☐ Rubber

Minor damage to: \_\_\_\_\_

Major damage to: \_\_\_\_\_

Size: Length: Feet: 40 Inches: 0 Width/Depth: Feet: 24 Inches: 0 Height: Feet: \_\_\_\_\_ Inches: \_\_\_\_\_

Men's Size: \_\_\_\_\_ Women's Size: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Comments:

Location of Asset: \_\_\_\_\_

For more information contact: \_\_\_\_\_