

Vehicle Inspection

Inventory ID	Asset Number	Fair Market Value:
Short Description: Year <u>2006</u> Make <u>Ford</u> Model <u>Explorer</u>		

<u>Please fill in or check</u> This vehicle: <input type="checkbox"/> Starts <input checked="" type="checkbox"/> Starts with a boost and <input checked="" type="checkbox"/> Runs <input type="checkbox"/> Does not run <input type="checkbox"/> For Parts Only Engine <u> </u> L, V <u> </u> <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel engine This vehicle was maintained every <u>3,000</u> <input type="checkbox"/> Days <input type="checkbox"/> Hours <input checked="" type="checkbox"/> Miles Condition: <input type="checkbox"/> Runs <input checked="" type="checkbox"/> Needs repair <input type="checkbox"/> is in unknown condition Repairs needed: <u>Battery drains, idling/stalling issues</u> Date Removed From Service: <u>2/2020</u> Maintenance Records: <input type="checkbox"/> Available <input checked="" type="checkbox"/> Not Available	<u>Long Description:</u> <u>Transmission</u> Transmission: <input checked="" type="checkbox"/> Automatic <input type="checkbox"/> Manual <u> </u> Speed Condition is: <input checked="" type="checkbox"/> Operable <input type="checkbox"/> Needs repair <input type="checkbox"/> Is Unknown Repairs Needed: <u> </u>
<u>Interior:</u> Color <u>Tan</u> <input checked="" type="checkbox"/> Cloth <input type="checkbox"/> Vinyl <input type="checkbox"/> Leather Minor damage to: <u>Driver's side rear door arm rest</u> Major damage to: <u> </u> Radio: Brand <u>No radio</u> <input type="checkbox"/> AM <input type="checkbox"/> AM/FM <input type="checkbox"/> AM/FM Cassette <input type="checkbox"/> AM/FM CD <input checked="" type="checkbox"/> AC <input type="checkbox"/> No AC Condition: <input type="checkbox"/> Cold <input checked="" type="checkbox"/> Unknown Air Bags <input checked="" type="checkbox"/> drivers side <input checked="" type="checkbox"/> dual <input checked="" type="checkbox"/> Cruise Control <input checked="" type="checkbox"/> Tilt Steering <input checked="" type="checkbox"/> Remote Mirrors <input type="checkbox"/> Climate Control Power: <input checked="" type="checkbox"/> Windows <input checked="" type="checkbox"/> Door Locks <input checked="" type="checkbox"/> Steering <input type="checkbox"/> Seats	
<u>Exterior:</u> Color <u>Silver</u> Windows: <input checked="" type="checkbox"/> No cracked glass <input type="checkbox"/> cracked <u> </u> Minor <input checked="" type="checkbox"/> Dents <input checked="" type="checkbox"/> Scratches <input checked="" type="checkbox"/> Dings Tire Condition: <input type="checkbox"/> Low <u> </u> <input type="checkbox"/> Flat <u> </u> Hubcaps <input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4 Minor dents to: <u>Scrapes driver's side rear near tail light</u> Major damage to: <u> </u> Decals: <input checked="" type="checkbox"/> None <input type="checkbox"/> Have been sprayed <input type="checkbox"/> Have been removed <input type="checkbox"/> Impressions remain <input type="checkbox"/> No impressions Emergency equip: <input type="checkbox"/> None <input checked="" type="checkbox"/> Has been removed <input type="checkbox"/> There are holes in the exterior <input checked="" type="checkbox"/> There are no holes Additional Equipment: Description <u> </u> Manufacturer <u> </u> Model <u> </u> Serial # <u> </u>	

Vehicle Info: VIN # <u>1FMEU72E46UB76046</u>	Mileage <u> </u>	Title Restriction <input type="checkbox"/> Y <input checked="" type="checkbox"/> N
Location of Asset: <u>Newton Town Hall, 39 Trinity St, Newton, NJ 07860</u> For more information contact: <u>973-383-3521</u>		

Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 15 minutes.